

Photo 15: Alignment of piles (marked by white flashes) at the NW corner of the engine house.



Photo 16: Brick wall and baulks of timber around chimney base.



Photo 17: Remains of retaining wall.




Photo 18: Ceramic insulator.

Photo 19:  
Fire irons  
cached  
outside rear  
of boiler  
room




Photo 20: Lock.